Unfortunately this is the run in which the, almost brand new, billet steel camshaft decided to fail, setting of a cataclysmic chain reaction..

Unfortunately this is the run in which the, almost brand new, billet steel camshaft decided to fail, setting of a cataclysmic chain reaction..

http://www.youtube.com/watch?v=SXLYWhTCeCU